

Emergency and exit lighting test

12 Example Street, Burleigh Heads QLD 4220

Checked on 21 October 2026 by Jordan Reed (licence 000000). 1 defect is listed below, 1 urgent.

Discharge test of each emergency and exit light, recorded in the log book, as AS/NZS 2293.2 sets out for 6-monthly testing.

Client

Burleigh Surf Supplies

Building or area

Shop, office and workshop

Next due

21 April 2027

Defects (1)

1. URGENT: Battery failed the discharge test

About: EL-05 Emergency light

EL-05 stayed lit for 45 minutes (90 needed). Replace the battery pack and retest.

General

Item	Result	Reading	Note
Exit signs visible and unobstructed	Pass		
Charge indicators lit on every fitting	Pass		

Fittings tested: log book (8)

Fitting	Where	Time lit	Result	Note
EL-01 Exit sign	Front entry	120 min	Pass	
EL-02 Exit sign	Rear fire door	115 min	Pass	
EL-03 Emergency light	Front office	110 min	Pass	
EL-04 Emergency light	Hallway	105 min	Pass	
EL-05 Emergency light	Workshop, north wall	45 min	Fail	Battery flat after 45 minutes. Replace the battery pack.
EL-06 Emergency light	Workshop, south wall	118 min	Pass	
EL-07 Exit sign	Workshop roller door	112 min	Pass	
EL-08 Emergency light	Storeroom	100 min	Pass	

Tested 21 October 2026 by Jordan Reed. Passes at 90 min or more.

Sign-off

Inspected by

Jordan Reed, licence 000000

Person on site

Signed by Chris Morgan on 21 Oct 2026, 2:15 pm (signature on the online report)

This report records what was seen and tested on the day, by the person named. It isn't a certificate of testing and compliance, and it doesn't cover parts of the installation that couldn't be seen or reached, or faults that appear later.