

# Test and tag register

Burleigh Surf Supplies · printed 21 Oct 2026

By Coastline Electrical · ABN 00 000 000 000 · Licence 000000 (QLD) · 0400 000 100

In-service inspection and testing to AS/NZS 3760.

**12 tagged items: 10 passed, 2 failed (out of service), 0 due within 30 days.**

Tested or serviced 21 Oct 2026 by Jordan Reed.

Site: 12 Example Street, Burleigh Heads QLD 4220

## Test instrument

Sample PAT-100 · serial SN 000123 · calibration due 14 Mar 2027



| Tag                                                                                | Item                                                                                           | Tested      | By          | Result | Readings                                                 | Next due       |
|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------|-------------|--------|----------------------------------------------------------|----------------|
| <b>12 Example Street, Burleigh Heads QLD 4220</b>                                  |                                                                                                |             |             |        |                                                          |                |
|    | CE0101 Kettle · Staff kitchen · Appliance or tool, Class I · Homeware K-17                     | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · Earth 0.06 ohm · IR >299 M ohm               | 21 Apr 2027    |
|    | CE0102 Microwave · Staff kitchen · Appliance or tool, Class I · Homeware MW-25 · SN MW25-88412 | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · Earth 0.09 ohm · IR >299 M ohm               | 21 Apr 2027    |
|    | CE0103 Toaster · Staff kitchen · Appliance or tool, Class I · Homeware T-2                     | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · Earth 0.11 ohm · IR 180 M ohm                | 21 Apr 2027    |
|    | CE0104 Extension lead, 15 m · Workshop · Extension lead, Class I                               | 21 Oct 2026 | Jordan Reed | Fail   | Visual failed                                            | Out of service |
|  | CE0105 Power board, 6 outlet · Front office desk 2 · Power board, Class I                      | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · Earth 0.12 ohm · IR >299 M ohm · Polarity OK | 21 Apr 2027    |
|  | CE0106 Cordless drill charger · Workshop · Appliance or tool, Class II · ToolCo C18            | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · IR >299 M ohm                                | 21 Apr 2027    |
|  | CE0107 Angle grinder · Workshop · Appliance or tool, Class II · ToolCo AG-125 · SN AG125-0457  | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · IR 210 M ohm                                 | 21 Apr 2027    |
|  | CE0108 Portable RCD · Workshop · Portable RCD, Class II                                        | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · Trip 22 ms                                   | 21 Apr 2027    |
|  | CE0109 Fan heater · Front office · Appliance or tool, Class I · Homeware FH-20                 | 21 Oct 2026 | Jordan Reed | Fail   | Visual OK · Earth 1.9 ohm                                | Out of service |
|  | CE0110 Computer monitor · Front office desk 1 · Appliance or tool, Class II · Screenly 24-FHD  | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · IR >299 M ohm                                | 21 Apr 2027    |
|  | CE0111 Computer monitor · Front office desk 2 · Appliance or tool, Class II · Screenly 24-FHD  | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · IR >299 M ohm                                | 21 Apr 2027    |
|  | CE0112 Extension lead, 10 m · Workshop · Extension lead, Class I                               | 21 Oct 2026 | Jordan Reed | Pass   | Visual OK · Earth 0.21 ohm · IR >299 M ohm · Polarity OK | 21 Apr 2027    |

## Failed / out of service

Tagged out of service. Don't use these until they're repaired and retested, or thrown out.


### CE0104 · Extension lead, 15 m · Workshop

Failed the visual inspection: cut in the outer sheath about 2 m from the plug, inner cores showing. Tagged out of service.



**CE0109 · Fan heater · Front office**

Earth continuity 1.9 ohm, over the limit. Loose earth in the plug top. Tagged out of service until repaired and retested.



**Tested by**

Jordan Reed · licence or competency no. 000000

Signature \_\_\_\_\_ Date \_\_\_\_\_

SAMPLE